MMTP Monitoring Committee: Observations at post-construction monitoring stations

Date:	May 24, 2023	Site: 124	
Weather:	Windy	Distance from access point:	
Start time:	9:00am	End time:	
Monitors:	Danyl Taylor Travis Bird.	Keith Kowall	
Vegetation			
Vegetation species observed			
Any invasive vegetation species? Yes / No			
Wildlife			
Wildlife or signs of wildlife observed	Greese flying Ducks Meadowlark		
Other observations Control of the Co			
Water level:	High / Medium / Low / No v	water Notes:	
Noise level:	Loud / Medium / Quiet	Notes:	
Visibility:	How visible is the site from the access point?		
	What else do you see from this site?		
Notes:	Construction on Y36V by Valand.		
	Jane gerbage		
	Some gerbage Chaned dramage ditch		